

# Shiploader and Walkway Inspection Port Kaiser, Jamaica



Enco provided field inspection, structural analysis and evaluation of the existing ship loader gantry, baghouse structure and two digestion walkways at Port Kaiser. The evaluation concentrated on structural deficiencies due to corrosion and operation wear, in addition to improper structural / mechanical design and installation resulting in structural failure.

## **Analysis supplied for upgrade**

- Detailed inspection
- Structural analysis
- Report – findings & recommendations